



Sample Receipt

Job : 18-28164

Client	Idom Merebrook Ltd	Contact	Linford Shacklady, Tim Crowe
Contract Title	Former RAF Upper Rissington	Phone	
Your Ref	17183	Fax	
PO Number	18-S1-FDO-LABS	Email	Ishacklady@idom.com;tcrowe@idom.com
Quote		Location	S12
Date Sampled	27/11/2018	Contract	
Date Received	29/11/2018	Coc	
Date Instructed	29/11/2018	Sample Types	10 soil samples
Date Logged	29/11/2018		
Date Due	05/12/2018		
Lab Notes	Note that any job which has subcontracted analysis may not be completed by the stated due date.		

1427773 - Wellington Road POS subsoil 1 0.00-0.10 2018-11-27 (S)(I)
1427774 - Wellington Road POS subsoil 2 0.00-0.10 2018-11-27 (S)(I)
1427775 - Wellington Road POS subsoil 3 0.00-0.10 2018-11-27 (S)(I)
1427776 - Wellington Road POS subsoil 4 0.00-0.10 2018-11-27 (S)(I)
1427777 - Wellington Road POS subsoil 5 0.00-0.10 2018-11-27 (S)(I)
1427778 - Wellington Road POS subsoil 6 0.00-0.10 2018-11-27 (S)(I)
1427779 - Wellington Road POS subsoil 7 0.00-0.10 2018-11-27 (S)(I)
1427780 - Wellington Road POS subsoil 8 0.00-0.10 2018-11-27 (S)(I)
1427781 - Wellington Road POS subsoil 9 0.00-0.10 2018-11-27 (S)(I)
1427782 - Wellington Road POS subsoil 10 0.00-0.10 2018-11-27 (S)(I)

Testing Scheduled



Sample Receipt

Job : 18-28164

Client	Idom Merebrook Ltd	Contact	Linford Shacklady, Tim Crowe
Contract Title	Former RAF Upper Rissington	Phone	
Your Ref	17183	Fax	
PO Number	18-S1-FDO-LABS	Email	Ishacklady@idom.com;tcrowe@idom.com
Quote		Location	S12
Date Sampled	27/11/2018	Contract	
Date Received	29/11/2018	Coc	
Date Instructed	29/11/2018	Sample Types	10 soil samples
Date Logged	29/11/2018		
Date Due	05/12/2018		
Lab Notes	Note that any job which has subcontracted analysis may not be completed by the stated due date.		

	1427773 - Wellington Road POS subsoil 1 0.00-0.10 2018-11-27 (S)(I) 1427774 - Wellington Road POS subsoil 2 0.00-0.10 2018-11-27 (S)(I) 1427775 - Wellington Road POS subsoil 3 0.00-0.10 2018-11-27 (S)(I) 1427776 - Wellington Road POS subsoil 4 0.00-0.10 2018-11-27 (S)(I) 1427777 - Wellington Road POS subsoil 5 0.00-0.10 2018-11-27 (S)(I) 1427778 - Wellington Road POS subsoil 6 0.00-0.10 2018-11-27 (S)(I) 1427779 - Wellington Road POS subsoil 7 0.00-0.10 2018-11-27 (S)(I) 1427780 - Wellington Road POS subsoil 8 0.00-0.10 2018-11-27 (S)(I) 1427781 - Wellington Road POS subsoil 9 0.00-0.10 2018-11-27 (S)(I) 1427782 - Wellington Road POS subsoil 10 0.00-0.10 2018-11-27 (S)(I)										
Testing Scheduled	X	X	X	X	X	X	X	X	X	X	X
Speciated PAH Soil by GCMS	X	X	X	X	X	X	X	X	X	X	X



Sample Receipt

Job : 18-28164

Client	Idom Merebrook Ltd	Contact	Linford Shacklady, Tim Crowe
Contract Title	Former RAF Upper Rissington	Phone	
Your Ref	17183	Fax	
PO Number	18-S1-FDO-LABS	Email	Ishacklady@idom.com;tcrowe@idom.com
Quote		Location	S12
Date Sampled	27/11/2018	Contract	
Date Received	29/11/2018	Coc	
Date Instructed	29/11/2018	Sample Types	10 soil samples
Date Logged	29/11/2018		
Date Due	05/12/2018		
Lab Notes	Note that any job which has subcontracted analysis may not be completed by the stated due date.		

1427773 - Wellington Road POS subsoil 1 0.00-0.10 2018-11-27 (S)(I)
1427774 - Wellington Road POS subsoil 2 0.00-0.10 2018-11-27 (S)(I)
1427775 - Wellington Road POS subsoil 3 0.00-0.10 2018-11-27 (S)(I)
1427776 - Wellington Road POS subsoil 4 0.00-0.10 2018-11-27 (S)(I)
1427777 - Wellington Road POS subsoil 5 0.00-0.10 2018-11-27 (S)(I)
1427778 - Wellington Road POS subsoil 6 0.00-0.10 2018-11-27 (S)(I)
1427779 - Wellington Road POS subsoil 7 0.00-0.10 2018-11-27 (S)(I)
1427780 - Wellington Road POS subsoil 8 0.00-0.10 2018-11-27 (S)(I)
1427781 - Wellington Road POS subsoil 9 0.00-0.10 2018-11-27 (S)(I)
1427782 - Wellington Road POS subsoil 10 0.00-0.10 2018-11-27 (S)(I)

Testing Scheduled

1 packages received.

Analysis is underway.

Packages received: 1 CB Received, AM
Soil, W - Water, L - Leadate, G - Gas, S - Subcontracted

Sample Comments

DETS cannot be held responsible for the integrity of sample(s) received whereby the laboratory did not undertake the sampling. In this instance samples received may be deviating.

Deviating Sample criteria are based on British and International standards and laboratory trials in conjunction with the UKAS note "Guidance on Deviating Samples".

All samples received are listed below. However, those samples that have additional comments in relation to hold time and/or inappropriate containers are deviating due to the reasons stated. This means that the analysis is accredited where applicable, but results may be compromised due to sample deviations.

If no sampled date (soils) or date/time (waters) has been supplied then samples are deviating. However, if you are able to supply a sampled date (and time for waters), this will prevent samples being reported as deviating where specific hold times are not exceeded and where the container supplied is suitable.

Lab No.	Sample ID	Date Sampled	Containers Received	Deviating due to holding time being exceeded for test(s)	Deviating due to inappropriate container for test(s)	Deviating due to headspace presence in container for test(s)
1427773	Wellington Road POS subsoil 1 0.00-0.10 SOIL	27/11/2018	Glass Jar 250ml			
1427774	Wellington Road POS subsoil 2 0.00-0.10 SOIL	27/11/2018	Glass Jar 250ml			
1427775	Wellington Road POS subsoil 3 0.00-0.10 SOIL	27/11/2018	Glass Jar 250ml			
1427776	Wellington Road POS subsoil 4 0.00-0.10 SOIL	27/11/2018	Glass Jar 250ml			
1427777	Wellington Road POS subsoil 5 0.00-0.10 SOIL	27/11/2018	Glass Jar 250ml			
1427778	Wellington Road POS subsoil 6 0.00-0.10 SOIL	27/11/2018	Glass Jar 250ml			
1427779	Wellington Road POS subsoil 7 0.00-0.10 SOIL	27/11/2018	Glass Jar 250ml			
1427780	Wellington Road POS subsoil 8 0.00-0.10 SOIL	27/11/2018	Glass Jar 250ml			

Sample Comments

DETS cannot be held responsible for the integrity of sample(s) received whereby the laboratory did not undertake the sampling. In this instance samples received may be deviating.

Deviating Sample criteria are based on British and International standards and laboratory trials in conjunction with the UKAS note "Guidance on Deviating Samples".

All samples received are listed below. However, those samples that have additional comments in relation to hold time and/or inappropriate containers are deviating due to the reasons stated. This means that the analysis is accredited where applicable, but results may be compromised due to sample deviations.

If no sampled date (soils) or date/time (waters) has been supplied then samples are deviating. However, if you are able to supply a sampled date (and time for waters), this will prevent samples being reported as deviating where specific hold times are not exceeded and where the container supplied is suitable.

Lab No.	Sample ID	Date Sampled	Containers Received	Deviating due to holding time being exceeded for test(s)	Deviating due to inappropriate container for test(s)	Deviating due to headspace presence in container for test(s)
1427781	Wellington Road POS subsoil 9 0.00-0.10 SOIL	27/11/2018	Glass Jar 250ml			
1427782	Wellington Road POS subsoil 10 0.00-0.10 SOIL	27/11/2018	Glass Jar 250ml			