

APPENDIX 9 ▪ Laboratory Certificates – Validation of Garden Formation

APPENDIX 10 ▪ Garden Sample Location Drawing

APPENDIX 11 ▪ Shrivenham Topsoil Suppliers Information

APPENDIX 12 ▪ Laboratory Certificate Shrivenham Topsoil

APPENDIX 13 ▪ Primary School and Community Centre Validation

APPENDIX 14 ▪ Potential Contaminant Hotspots Investigation

APPENDIX 15 ▪ Hawker Square Site Investigation Report

APPENDIX 16 ▪ South West Playing Field Investigation Report

- APPENDIX 17** ▪ Laboratory Certificate - South West Playing Field Remedial Excavation

- APPENDIX 18** ▪ Drawing - South West Playing Field Remedial Excavation Sample Locations

APPENDIX 19 ▪ Waste Soil Certificates

- APPENDIX 20** ▪ Laboratory Certificate – South West Playing Field Formation under Former Stockpile

APPENDIX 21 ▪ Photographic Record of South East POS Validation Sampling

APPENDIX 22 ▪ Drawing - South East POS Validation Sample Locations

APPENDIX 23 ▪ Laboratory Certificate - South East POS Validation Sample

APPENDIX 24 ▪ Area C Investigation Letter Report

APPENDIX 25 ▪ Drawing - Proposed Public House Area Sample Locations

APPENDIX 26 ▪ Laboratory Certificate - Proposed Public House Area Samples

APPENDIX 27 ▪ Drawing – Calor Gas Compound Sample Locations

APPENDIX 28 ▪ Laboratory Certificate – Calor Gas Compound Samples

APPENDIX 29 ▪ Laboratory Certificate – Disturbed Ground Formation Behind Shops

APPENDIX 30 ▪ Drawing – Sample Locations to Rear of Shops

APPENDIX 31 ▪ Drawing – Wellington Road Grassed POS Sample Locations

APPENDIX 32 ▪ Laboratory Certificates - Wellington Road Grassed POS Samples

APPENDIX 33 ▪ Drawing – Officers Mess POS Sample Locations

APPENDIX 34 ▪ Laboratory Certificate – Officers Mess POS Samples

APPENDIX 35 ▪ Laboratory Certificate – Wellington Road POS

APPENDIX 36 ▪ Drawing – Wellington Road POS Sample Locations

APPENDIX 37 Laboratory Certificate – Wellington Road POS Following Remedial Work

APPENDIX 38 ▪ Laboratory Certificate – Delfin Way Verge

APPENDIX 39 ▪ Primary School and Community Centre Validation

APPENDIX 40 ▪ Radman Validation Report

APPENDIX 41 ▪ Surface Water Monitoring Letter Reports

APPENDIX 42 ▪ Albion Water Site Assessment

APPENDIX 43 ▪ Officers Mess Stockpile Waste Tickets

APPENDIX 44 ▪ Recycled Aggregate Test Certificates

APPENDIX 45 ▪ Swindon Topsoil Suppliers Documentation

APPENDIX 46 ▪ Laboratory Certificate – Swindon Topsoil

APPENDIX 47 ▪ Drawing – Key Validation Areas and Report Sections

IDOM

IDOM Cromford Mills, Mill Lane, Matlock, Derbyshire DE4 3RQ
t +44 (0)1773 829 988 f +44 (0)1773 829 393 e info.derbyshire@idom.com **idom.com**

Registered in England No. 02740216 Registered office: as above

offices Birmingham London Kent Derbyshire Cardiff Manchester Stirling